

Global Change Notification (GCN)

Product Family	LAMP GUARD W/MTG. REFL. HOLES	10701503
		GCN Number
Series	Various	July 09, 2015
		Date Issued
Reason For Change	Supplier Change	
Change Description	This letter is to notify you that due to tooling end of life, and to maintain supply, Molex will be adding a new supplier for component parts used in our hazardous location rated 26W fluorescent handlamps. This change impacts primarily Engineering Numbers starting with 1090-HZ and related products such as reels that may have incorporated this handlamp. The component parts will be fully validated prior to production.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification from first article inspection	
Internal Molex Qualification Date (Planned Date Information Available)	September 07, 2015	
Sample Availability Date (Changed Part)	September 07, 2015	
Date of Implementation	September 18, 2015	
Method of Identifying Change	Shipping label date	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com